

ENEOS X PRIME AT Fluid

Highest performance fully synthetic ATF that provides high energy-saving, smooth acceleration, and lower noise.

ENEOS Motor oil Introducing our advanced automatic transmission fluid, meticulously crafted to enhance your vehicle's performance on a technical level. This cutting-edge lubricant is engineered to optimize energy utilization, resulting in remarkable energy-saving benefits. With its precision-engineered composition, it facilitates seamless acceleration, minimizing power loss and maximizing efficiency. Moreover, our specialized formulation reduces friction and vibration, significantly lowering noise levels within the transmission system. In essence, ENEOS X Prime AT Fluid is a technical marvel, delivering superior performance, fuel efficiency, and reduced noise for a truly refined driving experience as all-in-one products with the highest performance level.

SPECIAL FEATURES

1. Advanced Fully Synthetic Technology

ENEOS X PRIME AT Fluid is a fully synthetic automatic transmission fluid specially developed to meet Japanese OEM's required specifications (JASO M315 1A-LV). It also meets the requirements for DEXRON III, VI, Ford MERCON LV and so on.

2. High Energy Saving

ENEOS X PRIME AT Fluid is developed using Japanese technology to improve fuel economy and help to reduce energy loss without compromising fatigue prevention or anti-wear performance.

3. Smooth acceleration and Top-class ATF performance

ENEOS X PRIME AT Fluid has a very high viscosity index and allows smooth gear change even with cold start. It also has very good anti-oxidation, anti-wear and foaming characteristics, anti-corrosion properties and elastomer compatibility.

PERFORMANCE LEVEL

- Meet Japanese OEM's required specifications (JASO M315 1A-LV)
- Meets the requirements for DEXRON III, VI, Ford MERCON LV and so on

APPLICATION

Wide variety of automatic transmissions vehicles.

CONTAINERS

1L, 4L

TYPICAL PROPERTIES

Color	Red
Density (15°C), g/cm ³	0.8472
Flash point (COC), °C	214
Pour point, °C	< -45.0
Kinematic viscosity	
(40°C), mm ² /s	29.68
(100°C), mm ² /s	6.11
Viscosity index	160
Brookfield viscosity (-40°C), mPa·s	8300
Acid number, mgKOH/g	1.47
Base number, HClO ₄ , mgKOH/g	2.92
Foaming, seq.I, ml/ml	0/0
seq.II, ml/ml	0/20
seq.III, ml/ml	0/0

Note: The typical properties may be changed without notice (Oct 2023)



COMPATIBILITY OF ENEOS X PRIME AT FLUID

	Manufacturers	Compatibility
North American	Allison C-3	☑
	Allison C-4	☑
	Allison TES-389	☑
	Allison TES-389B	☑
	Allison TES-295	☑
	Chrysler SP- III	☑
	Chrysler AS68RC ATF	☑
	Chrysler 05127382AA	☑
	Chrysler 68043742AA	☑
	Chrysler 68333587AA	☑
	Chrysler 68092912AA	☑
	Chrysler 68171866AA	☑
	Chrysler 68218925AA	☑
	Chrysler 3403-M115	☑
	Chrysler ATF+	☑
	Chrysler ATF+2	☑
	Chrysler ATF+3	☑
	Chrysler ATF+4	☑
	Ford M	☑
	Ford XT-2 QDX	☑
	Ford XT-6 QSP	☑
	Ford XT-8 QAW	☑
	Ford XT-9- QMM5 for FNR5	☑
	Ford XT-10 QLV	☑
	Ford WSS-M2C-922-A1	☑
	Ford WSS-M2C-924-A	☑
	Ford ATF M-V	☑
	Ford Type F	NO
	Ford MERCON	☑
	Ford MERCON V	☑
	Ford MERCON LV	☑
	Ford MERCON SP	☑
	Ford FNR5 Automatic Transmisison Fluid (ATF)	☑
Ford Premium Automoatic Transmission Fluid (ATF)	☑	
Ford MERCON ULSV	Unknown	
GM Dexron B	☑	
GM Dexron IIC	☑	
GM Dexron IID	☑	



	GM Dexron III G	<input checked="" type="checkbox"/>
	GM Dexron III H	<input checked="" type="checkbox"/>
	GM Dexron VI	<input checked="" type="checkbox"/>
	GM Dexron HP	Unknown
	GM Dexron ULV	Unknown
	GM P/N 88900925	<input checked="" type="checkbox"/>
	GM P/N 9985010	<input checked="" type="checkbox"/>
	GM P/N 22689186	<input checked="" type="checkbox"/>
	GM P/N 19256039	<input checked="" type="checkbox"/>
	GM P/N 88863400	<input checked="" type="checkbox"/>
	GM P/N 88863401	<input checked="" type="checkbox"/>
	GM P/N 19 40 700	<input checked="" type="checkbox"/>
	GM P/N 19 40 767	<input checked="" type="checkbox"/>
	GM P/N 21005966	<input checked="" type="checkbox"/>
	GM W16444	<input checked="" type="checkbox"/>
Asian	Honda ATF Z-1	<input checked="" type="checkbox"/>
	Honda ATF DW-1	<input checked="" type="checkbox"/>
	Honda(Acura) Type 3.1	<input checked="" type="checkbox"/>
	Acura Type 3.0, Type 3.1	<input checked="" type="checkbox"/>
	Hyundai/Kia Genuine ATF	Unknown
	Hyundai/Kia P/N 00232-19023	<input checked="" type="checkbox"/>
	Hyundai/Kia SP-II	<input checked="" type="checkbox"/>
	Hyundai/Kia SP-III	<input checked="" type="checkbox"/>
	Hyundai/Kia JWS 3309	<input checked="" type="checkbox"/>
	Hyundai/Kia JWS 3314	<input checked="" type="checkbox"/>
	Hyundai/Kia JWS 3317	<input checked="" type="checkbox"/>
	Hyundai/Kia SP-IV	<input checked="" type="checkbox"/>
	Hyundai/Kia SP-IV M	<input checked="" type="checkbox"/>
	Hyundai/Kia SP-IV M1	<input checked="" type="checkbox"/>
	Hyundai/Kia SPH-IV	<input checked="" type="checkbox"/>
	Hyundai/Kia SP-IV RR	<input checked="" type="checkbox"/>
	Hyundai NWS-9638	<input checked="" type="checkbox"/>
	JASO 1-A	<input checked="" type="checkbox"/>
	JASO 1-A-LV	<input checked="" type="checkbox"/>
	Aisin Warner JWS 3309	<input checked="" type="checkbox"/>
	Aisin Warner JWS 3324	<input checked="" type="checkbox"/>
	Aisin Warner AW-1	<input checked="" type="checkbox"/>
	Aisin Warner AW-2	<input checked="" type="checkbox"/>
	Kia Red-1	<input checked="" type="checkbox"/>
	Isuzu ATF WSI	<input checked="" type="checkbox"/>
	Isuzu SCS	<input checked="" type="checkbox"/>
	Isuzu Genuine ATF	Unknown
	P/N 08200-9001	<input checked="" type="checkbox"/>
	Isuzu ATF II	<input checked="" type="checkbox"/>
	Isuzu ATF III	<input checked="" type="checkbox"/>
	Mazda T-IV / JWS3309	<input checked="" type="checkbox"/>



	Mazda JWS3317	<input checked="" type="checkbox"/>
	Mazda ATF A7	<input checked="" type="checkbox"/>
	Mazda ATF-M III	<input checked="" type="checkbox"/>
	Mazda ATF-MV	<input checked="" type="checkbox"/>
	Mazda ATF FZ	<input checked="" type="checkbox"/>
	Mobil 3324(Mazda Axcela Hybrid)	<input checked="" type="checkbox"/>
	Mitsubishi SP	<input checked="" type="checkbox"/>
	Mitsubishi SP-II	<input checked="" type="checkbox"/>
	Mitsubishi SP-III	<input checked="" type="checkbox"/>
	Mitsubishi ATF J2	<input checked="" type="checkbox"/>
	Mitsubishi ATF-J3	<input checked="" type="checkbox"/>
	Mitsubishi ATF-PA	<input checked="" type="checkbox"/>
	Mitsubishi SP-IV	<input checked="" type="checkbox"/>
	Nissan 402	<input checked="" type="checkbox"/>
	Nissan Matic-D	<input checked="" type="checkbox"/>
	Nissan Matic-J	<input checked="" type="checkbox"/>
	Nissan Matic-K	<input checked="" type="checkbox"/>
	Nissan Matic-W	<input checked="" type="checkbox"/>
	Nissan Matic-S	<input checked="" type="checkbox"/>
	Nissan Matic-G	Unknown
	Subaru ATF	<input checked="" type="checkbox"/>
	Subaru ATF-HP	<input checked="" type="checkbox"/>
	Suzuki 3314	<input checked="" type="checkbox"/>
	Suzuki Matic-D	<input checked="" type="checkbox"/>
	Suzuki Matic-J	<input checked="" type="checkbox"/>
	Suzuki Matic-S	<input checked="" type="checkbox"/>
	Suzuki 3317	<input checked="" type="checkbox"/>
	Toyota D-II	<input checked="" type="checkbox"/>
	Toyota T	<input checked="" type="checkbox"/>
	Toyota T-II	<input checked="" type="checkbox"/>
	Toyota T-III	<input checked="" type="checkbox"/>
	Toyota T-IV	<input checked="" type="checkbox"/>
	Toyota WS	<input checked="" type="checkbox"/>
European	Audi G 052 162	<input checked="" type="checkbox"/>
	Audi G 052 540	<input checked="" type="checkbox"/>
	Audi G 052 990	<input checked="" type="checkbox"/>
	Audi G 055 005	<input checked="" type="checkbox"/>
	Audi G 055 025	<input checked="" type="checkbox"/>
	Audi G 055 162	<input checked="" type="checkbox"/>
	Audi G 060 162	<input checked="" type="checkbox"/>
	Bentley P/N PY112995PA	<input checked="" type="checkbox"/>
	BMW ATF 7	<input checked="" type="checkbox"/>
	BMW 7045E	<input checked="" type="checkbox"/>
	BMW 8072B	<input checked="" type="checkbox"/>
	BMW LA 2634	<input checked="" type="checkbox"/>



BMW LT 71141	<input checked="" type="checkbox"/>
BMW PIN 81 22 9 400 272/275	<input checked="" type="checkbox"/>
BMW PIN 81 22 9 407 858/859	<input checked="" type="checkbox"/>
BMW PIN 83 22 0 024 249	Unknown
BMW PIN 83 22 0 024 359	<input checked="" type="checkbox"/>
BMW PIN 83 22 0 026 922	<input checked="" type="checkbox"/>
BMW PIN 83 22 0 142 516	<input checked="" type="checkbox"/>
BMW PIN 83 22 0 163 514	Unknown
BMW PIN 83 22 0 397 114	<input checked="" type="checkbox"/>
BMW PIN 83 22 0 403 248	<input checked="" type="checkbox"/>
BMW PIN 83 22 0 403 249	<input checked="" type="checkbox"/>
BMW PIN 83 22 2 152 426	<input checked="" type="checkbox"/>
BMW PIN 83 22 2 220 438/440	<input checked="" type="checkbox"/>
BMW PIN 83 22 2 289 397(ATF3)	<input checked="" type="checkbox"/>
BMW PIN 83 22 2 289 720(ATF3+)	<input checked="" type="checkbox"/>
BMW PIN 83 22 2 305 396	<input checked="" type="checkbox"/>
BMW PIN 83 22 2 305 397	<input checked="" type="checkbox"/>
BMW PIN 83 22 2 355 599	Unknown
BMW PIN 83 22 2 355 601	Unknown
BMW PIN 83 22 7 542 290	<input checked="" type="checkbox"/>
BMW PIN 83 22 9 407 765	<input checked="" type="checkbox"/>
BMW PIN 83 22 9 407 807	<input checked="" type="checkbox"/>
Citroen Z000169756	<input checked="" type="checkbox"/>
Jaguar WSS-M2C922-A1	<input checked="" type="checkbox"/>
Jaguar JLM 20238	<input checked="" type="checkbox"/>
Jaguar JLM 20292	<input checked="" type="checkbox"/>
Jaguar Fluid 8432	<input checked="" type="checkbox"/>
Jaguar 02JDE26444	<input checked="" type="checkbox"/>
Jaguar K17	<input checked="" type="checkbox"/>
Jaguar MERCON LV	<input checked="" type="checkbox"/>
MAN 339A	<input checked="" type="checkbox"/>
MAN 339D	<input checked="" type="checkbox"/>
MAN 339F	<input checked="" type="checkbox"/>
MAN 339 Type V-1	<input checked="" type="checkbox"/>
MAN 339 Type Z-1	<input checked="" type="checkbox"/>
MAN 339 Type Z-2	<input checked="" type="checkbox"/>
MAN 339 Type Z-3	<input checked="" type="checkbox"/>
MAN 339 Type V-3	Unknown
Porsche P/N 000 043 204 63	Unknown
Porsche P/N 000 043 205 28	<input checked="" type="checkbox"/>
Porsche P/N 000 043 304 00	Unknown
Porsche P/N 999 917 547 00	<input checked="" type="checkbox"/>
Porsche P/N 000 043 205 09	<input checked="" type="checkbox"/>
Renault Matic-D2	<input checked="" type="checkbox"/>
RollsRoyce PL 31493PA	Unknown



Land Rover P/N TYK500050	<input checked="" type="checkbox"/>
Land Rover Txaco ETL-7045E	<input checked="" type="checkbox"/>
Land Rover AW-1	<input checked="" type="checkbox"/>
Land Rover JWS3309	<input checked="" type="checkbox"/>
Land Rover Txaco N402	<input checked="" type="checkbox"/>
Land Rover MERCON SP	<input checked="" type="checkbox"/>
Land Rover 83 229 407 807	<input checked="" type="checkbox"/>
Land Rover LR 0232-89	Unknown
Land Rover DEXRON III	<input checked="" type="checkbox"/>
Maserati	Unknown
Mercedes-Benz MB 236.1	<input checked="" type="checkbox"/>
Mercedes-Benz MB 236.2	<input checked="" type="checkbox"/>
Mercedes-Benz MB 236.3	<input checked="" type="checkbox"/>
Mercedes-Benz MB 236.5	<input checked="" type="checkbox"/>
Mercedes-Benz MB 236.6	<input checked="" type="checkbox"/>
Mercedes-Benz MB 236.7	<input checked="" type="checkbox"/>
Mercedes-Benz MB 236.8	<input checked="" type="checkbox"/>
Mercedes-Benz MB 236.9	<input checked="" type="checkbox"/>
Mercedes-Benz MB 236.10	<input checked="" type="checkbox"/>
Mercedes-Benz MB 236.11	<input checked="" type="checkbox"/>
Mercedes-Benz MB 236.12	<input checked="" type="checkbox"/>
Mercedes-Benz MB 236.13	Unknown
Mercedes-Benz MB 236.14	<input checked="" type="checkbox"/>
Mercedes-Benz MB 236.15	<input checked="" type="checkbox"/>
Mercedes-Benz MB 236.16	<input checked="" type="checkbox"/>
Mercedes-Benz MB 236.17	<input checked="" type="checkbox"/>
Mercedes-Benz MB 236.41	<input checked="" type="checkbox"/>
Mercedes-Benz MB 236.81	Unknown
Mercedes-Benz MB 236.82	Unknown
Mercedes-Benz MB 236.91	Unknown
PSA AL-4	<input checked="" type="checkbox"/>
Renault DP-0	<input checked="" type="checkbox"/>
Saab P/N 93 160 393	<input checked="" type="checkbox"/>
Saab 93 165 147	<input checked="" type="checkbox"/>
Saab ATF HP	Unknown
VoithH55.6335	<input checked="" type="checkbox"/>
Voith H55.6336	<input checked="" type="checkbox"/>
Volvo P/N 1161521	<input checked="" type="checkbox"/>
Volvo P/N 1161621	<input checked="" type="checkbox"/>
Volvo P/N 1161540	<input checked="" type="checkbox"/>
Volvo P/N 1161640	<input checked="" type="checkbox"/>
Volvo P/N 31256774	<input checked="" type="checkbox"/>
Volvo P/N 31256675	<input checked="" type="checkbox"/>
Volvo 97340	<input checked="" type="checkbox"/>



Volvo 97341	<input checked="" type="checkbox"/>
VW G 052 162	<input checked="" type="checkbox"/>
VW G 052 533	Unknown
VW G 052 540	<input checked="" type="checkbox"/>
VW G 052 990	<input checked="" type="checkbox"/>
VW G 055 005	<input checked="" type="checkbox"/>
VW G 055 025	<input checked="" type="checkbox"/>
VW G 055 162	<input checked="" type="checkbox"/>
VW G 055 540	<input checked="" type="checkbox"/>
VW G 060 162	<input checked="" type="checkbox"/>
ZF TE-ML 02F	<input checked="" type="checkbox"/>
ZF TE-ML 03D	<input checked="" type="checkbox"/>
ZF TE-ML 04D	<input checked="" type="checkbox"/>
ZF TE-ML 05L	<input checked="" type="checkbox"/>
ZF TE-ML 09	<input checked="" type="checkbox"/>
ZF TE-ML 11A	<input checked="" type="checkbox"/>
ZF TE-ML 11B	<input checked="" type="checkbox"/>
ZF TE-ML 14A	<input checked="" type="checkbox"/>
ZF TE-ML 14B	<input checked="" type="checkbox"/>
ZF TE-ML 14C	<input checked="" type="checkbox"/>
ZF TE-ML 16M	Unknown
ZF TE-ML 16L	<input checked="" type="checkbox"/>
ZF TE-ML 17C	<input checked="" type="checkbox"/>
ZF TE-ML 20C	Unknown
ZF TE-ML 21L	<input checked="" type="checkbox"/>
ZF Lifeguard Fluid 5	<input checked="" type="checkbox"/>
ZF Lifeguard Fluid 6	<input checked="" type="checkbox"/>
ZF Lifeguard Fluid 6+	<input checked="" type="checkbox"/>
ZF Lifeguard Fluid 8	<input checked="" type="checkbox"/>

THE RECOMMENDATIONS OR SUGGESTIONS MADE IN THIS SHEET ARE MADE WITHOUT GUARANTEE OR REPRESENTATION AS TO RESULTS. THE CONTENT OF THIS SHEET IS CORRECT TO THE BEST OF OUR KNOWLEDGE. WE ADVISE THE READER TO CAREFULLY EVALUATE THE PRODUCT CHOICE FOR CRITICAL APPLICATIONS TOGETHER WITH THE SUPPLIER. WE DO NOT ACCEPT RESPONSIBILITY FOR DAMAGE AS A CONSEQUENCE OF INCOMPLETENESS OR NEGLIGENCE AND INACCURACIES IN THIS INFORMATION SHEET. ALL TERMS OF SALE OF THE SUPPLIER CAN BE APPLIED HERE.